1978-0363

TECHNICAL PROGRESS REPORT 381 NOTS TP 3674 COPY 1

TECHNICAL LIBINARY AFICHIVES
TECHNICAL III FRANCH DEPARTMENT
T

624A SOLID-PROPELLANT MOTOR IMPACT TEST

Dy

Robert F. Varwork & Frederick H. Weals
Tost Department

ABSTRACT. At the request of the Air Force Systems Command, a preprototype version of the 624A motor, with a single center segment plus end closures, was impacted into a massive concrete, steel, and earth target at a velocity of 667 fps to determine the hazard potential of the motor. Photographic data showed extensive grain breakup from the impact, and blast-gage data indicated a low range of overpressure and impulse forces. Fragments of motor case were thrown to 2,500 ft, and pieces of burning propellant were thrown to 3,000 ft.

This report presents a description of the test setup, procedures, results, and conclusions.

Distribution Statement A: Approved for public release; distribution is unlimited.



U.S. NAVAL ORDNANCE TEST STATION

China Lake, California

October 1964

188 809 QU

U. S. NAVAL ORDNANCE TEST STATION

AN ACTIVITY OF THE BUREAU OF HAVAL WEAPONS

J. I. HARDY, CAPT., USN
Commander

WM. B. McLEAN, Ph.D. Technical Director

FOREWORD

On 13 June 1964, a preprototype, heavy case, static firing version of the 624A solid-propellant motor was impacted against a concrete, steel, and earth target at a velocity of 667 fps off the muzzle of the Supersonic Navel Ordnance Research Track (SNORT). The test was conducted to aid in evaluating the potential hazard of the motor when used as the booster of a Titan III C missile.

This report, which has been reviewed and approved by the Space Systems Division, presents a description of the test setup, procedures, results, and conclusions.

The work was funded by the Space Systems Division of the Air Force Systems Command on MIPR No. SS-64-SSD-12 (Local Project No. 886).

Released by IVAR E. HIGHBERG Head, Test Department 21 August 1964

Under authority of WM. B. McLEAN Technical Director

NOTS Technical Publication 3674 Technical Progress Report 381

										Test Department
Manuscript			•		•		•			30/MS-680
Supersedes										TPR 381, Advance Copy
Collation .						•		Cover,	16	leaves, abstract cards
Pirst printin	g									. 105 numbered copies

CONTENTS

Introduction .

Test	Setup														,						1
	st Item																				1
_	st Vehicl	ρ.						•													2
	rget Conf							•	•		•										2
	strumenta	_							-				_			_	_		_	_	3
	Procedur			•	•	•	•	•	:	•	•	•	•	•	•	•	•	•	•	•	Į;
				-	-	-		•		•	•	•	•	•	•	•	•	•	•	•	4
	eliminary							•	•	•	•			•	•	•	•	•	•	•	
Mo	tor Assem	bly	•	•	•	•	•	•	•	•	•			•	•	•	•	•	•	•	l
Te	st Firing		•		•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	6
Test	Results	•						•	•			•	•	•	•	•	•	•	•	•	6
Pho	otographi	e D	ata					•	•				•		•	•	•	•	٠	•	6
	Lemetry D				•			•					•			•		•	•		7
	essure Ga																				7
	lusions										_		_					_	_		ġ
oone.	LUDZOMO	٠	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	-	•	•	
								_			•										
Table	es:																				
_	_		_																		_
1.	Overpres			_		•	• _	• .	•	• .	•	•	•	•	•	•	•	•	•	•	1
2.	Hozard E											on	•	•	•	•	•	•	•	•	2
3.		sur	e a	nd :	Imp	116	e D	ata	•	•	•	•	•	•	•	•	•	•	• •	•	8
4.	TWT Equi	val	enc	y Va	alu	25	•	•	•	•	•	•	•	•	•	•	•	•	•	•	10

Figures:

1.	Target Used in 624A Motor Impact Test	•		12
2.	Enlarged Film Frame Showing Typical Blast Cage Installation			13
3.	Pressure Gage Location Chart	•		13
4.	Camera Layout Used in Hazard Evaluation Test	•		14
5.	Installation of Aft Sled Ring	•		15
6.	Rotation of Test Motor Before Being Mounted on Track			16
7.	Motor Ready for Firing	•	•	16
8.	Enlarged Sequential Film Frames Showing Motor Impact	•	•	17
9.	Photographic Sequence After Motor Impact as Viewed From a			
	Distance of 4.1 Miles	•	•	18
10.	Typical Pieces of Unburned Propellant	•	•	19
11.	Typical Residue From Burned Propellant	•	•	19
12.	Forward Closure · · · · · · · · · · · · · · · · · · ·	•	•	20
13.	Debris to East of Target	•	•	20
14.	Debris to West of Target	•	•	21
15.	Debris to North of Target	•	•	21
16.	Debris and Crater at Target Site	•	•	22
17.	Target as Viewed From Track Muzzle Before and After Test .	•		23
18.	Dispersion of Fragments	•		24
19.	Montage Showing Large Pieces of Debris	٠		25
20.	Sections of Telemetry Record Obtained During Test	•		26
21.	Graph Showing Overpressure Vs. Distance	٠		27
22.	Graph Showing Impulse Vs. Distance	٠		28
23.	Typical Blast Gage Records	•	•	29

INTRODUCTION

This report documents a test conducted on the Supersonic Naval Ordnance Research Track (SNORT), at the request of the Space Systems Division of the Air Force Systems Command, to obtain information relating to the hazard potential of the 624A solid-propellant motor. (Two multisegment 624A motors are to be used as the zero stage of the Titan III C vehicle.)

The test item, a preprototype, heavy case, static firing version of the 624A motor equipped with a single center segment, was impacted at a velocity of 667 fps into a concrete, steel, and earth target placed 100 ft from the muzzle end of the track. The test approximated a fall-back condition from an altitude in excess of 10,000 ft with impact on a hard surface.

Test setup, procedures, results, and conclusions are described below.

TEST SETUP

Test Item

The motor tested was manufactured by the United Technology Center, Sunnyvale, California. It differed from flight hardware in that it had a heavier motor case, was equipped with only one cylindrical center segment instead of five, and was, therefore, considerably shorter than the actual stage-zero motor complex of Titan III C. The test motor was 120 in. in diameter, approximately 16 ft long (without the nozzle), and had a 3/4-in. steel case. It had a forward and an aft closure, both of which had skirts that allowed the sled rings to be bolted to the test item; an igniter and igniter adapter; a nozzle having a 6-deg upward cant; and one cylindrical segment. Component weights were as follows:

Loaded cylindrical segment Loaded forward closure Loaded aft closure Igniter adapter Igniter (RP-3) Nozzle Miscellaneous motor hardware	77,805 1b 23,860 23,211 160 122 3,202 150
Total motor weight	128,510 lb
Total propellant weight (before firing)	92,543
Approximate propellant weight at impact	82,000

Test Vehicle

The test sled consisted of two rings, four trucks (two forward and two aft), and l4 isolation skids -- three for each forward truck and four for each aft truck. The rings were designed to bolt to the skirts of the forward and aft closures of the motor during motor assembly. Since the motor had to be assembled in the vertical position, the rings were designed with trunions to accommodate the cranes used to hold the motor while it was being rotated to the horizontal position and placed on the track.

The tracks were the links between the rings and the isolation skids that fit on the rail heads. The skids were isolated from the tracks by rubber in the pin connection to reduce the track-induced vibration experienced by the motor during the run. The tracks and the skids were placed on the track, and the motor (bolted to the rings) was lowered onto them.

Target Configuration

The target face was constructed of reinforced concrete 6 ft in depth with a 20 x 20-ft impact surface. The concrete face was backed with 3-in. steel plate and this, in turn, was backed with approximately 35 ft of earth fill, 20 ft high. The concrete was prefabricated in blocks and placed in position 100 ft off the muzzle end of the track. The target impact surface had openings to accept the sled trucks to insure that the test item experienced initial contact. Figure 1 is a view of the target before the test.

Figures 1-23 appear at the end of the report beginning on page 12.

Instrumentation

Instrumentation included overpressure gages, seismographs, geophones, cameras, and radio-link telemetry. Because of the many unknown factors in this test, the choice of instrumentation was somewhat arbitrary in some areas. It was chosen in an effort to obtain optimum coverage by using a combination of suggestions from all groups concerned.

Overpressure Gages. Overpressure was measured with Kistler piezoelectric and Ballistics Research Laboratory (BRL) gages. The Kistler
gages use remotely controlled Ampex FRIOO tape recorders to collect data;
the BRL gages have a self-contained recording device. The pressure is
sensed on a diaphragm that is attached to a stylus. The stylus scribes
the diaphragm movements on an aluminum-coated glass disc. The disc is
retated by a chronometrically governed DC drive motor. Diaphragus rated
to measure anticipated overpressures were placed in the gages. Figure 2
shows a typical gage installation. Both types of gages were mounted to
get side-on, pressure-time data. The Kistler transducer was mounted at
the top of the horizontal section of tubing shown in the photograph. The
BRL gages were mounted flush with the ground surface.

Locations of pressure sensors are shown in Fig. 3; Table 1 lists types of Kistler gages and the nominal pressure ranges of the BRL instruments used at the various gage positions. The Air Force Rocket Propulsion Laboratory, Edwards AFB, California, provided consulting services for the gage layout and provided the Kistler gages. (Table 1 is repeated on page 13 for reader convenience.)

TABLE 1. Overpressure Gages

Position (ft)	Leg #1 (North)	Leg #2 (Vest)	Leg ∮3 (Southeast)
Å		Kistler - COLA BRL - 100 psi	BRL - 90 psi
154		Kistler - 601A BRL - 50 psi BRL - 25 psi	BRL - 25 pai
c 266		Kistler - folk BRL - 15 pat BRL - 5 pat	Kiatler - COLA BRL - 15 pai BRL - 5 pai
215 D	Bal - 5 psi	Kistler - 701A BRL - 5 pst BRL - 1 pst	Mistier - COLA BRL - 1 pai
E 1,1%	ist - 1 pei	BKL -) pol	Elather - 701A ERL - 0.5 per
† 1,500	##L - 0.5 p±i		ML - 0.5 pti

Seismograph and Geophone Installations. Personnel of the Division of Seismology, Coast and Geodetic Survey, Department of Commerce, instrumented the NOTS range area with seismographs and geophones to gather seismic data from the test. These data have been documented.*

Range Photography. The four major range camera functions were (1) surveillance of the motor during the run, (2) surveillance of the motor at impact, (3) gathering of velocity data from track muzzle to target impact, and (4) gathering of data on fireball growth.

Table 2 lists camera types, positions, lens sizes, frame rates, types of film, fields of view, and information to be recorded. Figure 4 is a camera layout sketch in which the camera numbers correspond to those listed in Table 2. NOTE: N, E, and W figures denote distances in feet from a common point at breech end of track. N = northerly along track, E and W = east or west of track centerline. This note applies throughout the entire report.

Telemetry. A six-channel FM/FM telemetry package was mounted in the forward left-hand truck of the test vehicle to gather motor environmental data during the run. One purpose of recording TM data was to be able to determine the cause of malfunction in case of a gross failure of the motor during the run. The functions monitored included vertical and lateral vibration on the forward and aft rings, linear acceleration, and combustion chamber pressure.

TEST PROCEDURES

Preliminary Preparations

First, an assembly area was constructed at track station 17,700 ft north (4,000 ft from the target face) and the necessary roadwork was done. Then, the week before the test motor arrived at NOTS, the target was assembled and overpressure instrumentation preparation was started. The motor was delivered to the range four days before the test and motor assembly was started the next day.

Motor Assembly

The motor was transported in three major units—the forward closure with igniter installed, the cylindrical segment, and the aft closure with nozzle installed. The motor was assembled in the vertical, nozzle—up position and rotated to the horizontal position with two 90-ton cranes, then placed on the sled trucks. Assembly and rotation took two days. Figure 5 shows the aft sled ring being put in position; Fig. 6 shows the motor being rotated to the horizontal position.

Scismic Disturbances Generated by Titan III 624A Solid Notor Test," by W. V. Mickey and T. R. Shugart, October 1964.

TABLE 2. Eazard Evaluation Camera Instrumentation

		Camera numbers and lo	catlons	correspon	d to the	layout shown in Fig. 4.	
Ce	mers number and type	Location	Lens	Hate (pps)	ملاع	Pield of view	Renarks
1.	Pastex 16 WP-3	17,000'F x 30'E	6*	2,000	Color	Hear pt. 17,650'3 30' wert x 1,800' har	Monitor ignition 500' trevel
2,	Milliken 16m	19,300'R x 30'E	6*	400	Color	Far pt. 17,700'H Sear pt. 18,900'H 60' vert x 1,200' hor	Monitor 1,200' travel
3.	Killiken 16en	20,300'# x 30'E	6*	400	Color	Far pt. 18, 500'H Hear pt. 19,600'H 60' wert x 1,200' hor	Mositor 1,200' tracel
4.	Photo-Socies 10B	21,500 H x 1,100 E	7"	360	Color	21,400'8 - 21,700'8	Monitor 200' travel, free flight, impact
5.	Pastan 16 WP-b	21,700'# x 1,100'E	9"	6,000	Color	30' vert x 52' her	Medium shot of item on target face
6.	Pastax 16 VP-3	21,700'E x 1,100'E	15"	2,000	Color	17' vert x 31' bor	Closeup of item on target face
7.	Pastax 16 W-4	21,700'A × 1,100'E	4*	4,000	SCOOL	66' vert x 125' hor	Firetall
5.	Milliken 16==	21,700'n x 1,100'R	1000	7-00	Color	19,600 π - 20,600 π	Travel from 19,600'S to 20,600'S
9.	Milliken 1622	21,700'# x 100'E	1000	1400	Color	20,600'N - 21,600'N	Travel from 20,600's to 21,600's
10.	Pastax 16 M7-3	21,690'# x 320'E	6"	4,000	Color	13' vert x 19' har	Closeup of impact of item on target
и.	Fastex 16 WP-3	21,690'N x 320'B	12=n	4,000	Color	1;0' vert x 220' hor	Fragment distribution
12.	Pastax 16 NF-3	21,690'n x 320'W	۲-	4,000	0c).or	13' vert x 19' hor	Closeup of impact of item on target
13.	Pastax 16 WF-3	21,690'# x 320'W	1200	4,000	Color	150' vert z 220' bor	Pregnent distribution
14.	Festex 16 WF-4	21,700 x 1,100 צי	9"	6,000	Calor	30' vert x 52' har	Medium shot, item impact
15.	Pastax 16 Wr-3	21,700 × 1,100 W	15"	2,000	Color	17' vart x 31' har	Closerp of item impact
16.	Faster 16	21,700 x 1,100 עי	Ļ-	L,000	ECCOOR	(6' vert x 125' har	Fireball
3.7 -	Photo-Sonica 48 35cm	21,700 אי 1,100 אי	6-3-	2,000	Color	21,600'8 - target	Velocity in free flight
18.	Photo-Sonics 10 16cm	21,700°π x 1,100°W	3"	1,000	Color	21,550'N - target	Free flight and impact
19.	Photo-Sonics 48 35mm	10,000'# x 3,000'B	75"	500	Oal or	H-65 tracking	On S-A road
ю.	Milliken 15mm	10,000'# x 3,000'E	24*	460	Color	8±5 tracking	Ca 3-4 roes
21.	Photo-Sonics 10A 70mm	10,000,E × חימפס,01	150*	to	Ool cor	Mak5 tracking	tuon 44 of
2	Photo-Sunica 1B 16mm	21,680'# x 100'E	1"	1,00	Outor	30" vert x 45" bor	Cose impact data
23.	Photo-Socies 18 16cm	21,690°# x 100°W	1	1,000	Oalur	jo' vert x \$5" bor	Oras impart data

The day before the test, the telemetry package was installed and checked out; the destruct receiver and decoder were mounted on the motor, and the motor was prepared for firing with the exception of installing the initiator and destruct charges. Instrumentation checkouts were in progress during the week. Figure 7 shows the motor ready to be fired.

Test Firing

The test was fired at 1320 hours on 13 June 1964. The motor performed as predicted for the 4,000-ft run, striking the target at a measured velocity of 667 fps. The 100 ft of motor free-flight from the track muzzle to the target was as ballistic studies had predicted and the sled trucks entered the target access holes so that the motor igniter made first contact with the target. The following atmospheric conditions existed at the time of the test:

Wind 8.5 fps from 180 deg
Temperature 94.5°F
Rhmidity 13%
Atmospheric pressure 926.3 millibars
Density 0.00204 slugs/ft³

TEST RESULTS

Photographic Data

Surveillance film shows that the motor penetrated approximately six ft into the target before failures were apparent. The case expanded and cracked at the forward end of the motor in both quadrants on the west side. The cracks propagated to the aft end of the segment as the motor tried to penetrate deeper. The first sign of fire came from the front of the motor after target penetration. After the motor had entered the target to approximately half the motor length, the aft closure ruptured around the nozzle followed by complete destruction of the motor. Figure 8 shows enlarged lemm film sequence of motor impact. The force of the explosion left a crater approximately seven ft deep where the target had been.

Figure 9 is a series of pictures of the propellant after it was expelled from the motor (burning propellant was thrown as far as 3,000 ft from the impact point). Figure 10 is a sample of the size of the pieces of unburned propellant, most of which was found along the track. The total amount of unburned propellant was quite small. Residue on the ground surface left by the impact of the burning propellant was roughly circular in shape and varied from two inches to ten feet in diameter. The sand was melted and the residue had the appearance of aluminum.

Figure 11 shows typical residue from burned propellant. The forward closure (Fig. 12) was found 270 ft beyond the target site. Figures 13, 14, and 15 show the debris to the east, west, and north of the target location; Fig. 16 shows the nozzle and other debris in the crater; Figure 17 shows the target face from the track muzzle before and after the test. Travel of some fragments was found as shown in Fig. 18. Descriptions of the fragments are keyed to the numbers in the graph. Figure 19 is a montage showing large pieces of debris found between 1,260 and 2,500 ft from point of impact (see note, page 4).

Telemetry Data

The firing pulse was sent from the SWORT programmer at zero time, and all the following events, taken from the TM record, are referenced to that time:

Moter ignition	am 90S+0
Sled first motion	0+443 ms
Time of impact	0+13.307 sec
Thrust-chamber pressure	+550 psi
Average acceleration	-12.4g

Data from the four vibration channels were not assessed since they are not pertinent to the evaluation of the test. Sections of the TM record are shown in Fig. 20.

Pressure Cage Data

The chief source of data from the overpressure instrumentation came from the BRL gages. There was a failure of the Kistler gage recorder on leg #2 and no information was recorded by the Kistler gages at that location. The failure could not be reproduced after the test; therefore, the cause is unknown. However, Kistler gages at distances of 512 and 1,130 ft on leg #3 apparently provided valid overpressure data which, in general, agreed with the data obtained from the BRL gages at the same locations. Additionally, all three Kistler gages on leg #3 yielded time of arrival of the shock wave.

Table 3 gives the gage stations, heak overpressures, duration of overpressure wave, and impulses as computed for the ERL gages by the Ballistics Research Laboratory and 11. the Kistler gages by the U. S Naval Ordnance Test Station. Figure 21 is a graph of the overpressures compared to reference curves for 4,100, 8,200, and 16,400 lb of TRT, as derived from BRL Memorandum Report No. 1518*; Fig. 22 is a plot of impulse measurements using reference curves for the above amounts of TRT, as derived from a scaled impulse versus scaled distance curve prepared by C. Kingery of BRL.**

TABLE). Overpressure and impulse Data

Station	Distance (ft)	Overpressure (psi)	Pulse Duration (ms)	lmpulse (psi - ms)
ZFL CACES				
Leg #1 Borth				
D	515	1.4	70.5	10.2
<u>2</u> F	1,130	0.526	81.2	13.2
F	1,500	0.324	86.1	13.5
Log ∮2 West		ļ	!	
A	92.	24.4	34.1	250.
В	154	11.8	19.9	134.
B C	154	n.0	12.5	145.
С	266	1, 1	19.2	75-3
C D	266	4.2	98.5	93.8
D	215	5.0	68.7	49.8
פ	512	No Record		
Ľ	1,130	No Record		·
Leg #3 (32)				
٨	21	42.3	1 61.9	541.
B	154	Poor Record	l 1	••
Ċ	266	9.0	1 49.7	150.5
c ·	266	7.9	50.3	163.5
מ	512	2.07	70.1	66.2
Ł	1,130	0.763	88.2	29.1
7	1,500	0.414	115.9	20.8
CISTLER CAGES				
Leg #2 Vest	No Record			
Leg #3 (52)				
С	Poor Record			
Ď	512	2.1	47.	47.
E	1,130	0.66	89.	29.

Ballistics Research Laboratory. "Peak Overpressure Vs. Scaled Distances for TFT Surface Bursts." April 1964. BRL Memorandum Report No. 1518. This report covers measurements made on 5., 20., and 100-ton hemispherical charges.

ton TNT surface bursts and was transmitted to KOTS by BRL letter, C. N. Kingery/sri/31258, dated 11 September 1964.

The times of arrival of the overpressure wave were taken from the Kistler gage record on the southeast leg. The times are taken from 9 ms after initial impact (as measured by sledborne telemetry) to the leading edge of the overpressure pulse and are as follows:

266 ft from impact - 145 ms
- 512 ft from impact - 324 ms
1,130 ft from impact - 844 ms

The 9 ms cited above is an approximation accounting for the interval between impact and initial rapid expansion of the fireball.

The average velocities of the pressure wave calculated from the distances and times listed above are as follows:

From target to 266 ft - 1,834 fps From 266 ft to 512 ft - 1,374 fps From 512 ft to 1,130 ft - 1,188 fps

CONCLUSIONS

Inspection of individual values for overpressure and impulse shows a tendency for gages close to the target on the southerst leg (#3) to run higher than corresponding gages on the west leg (#2). Gage records from the north leg (#1) ran lower than those from corresponding positions on the west and southeast legs. This is anticipated behavior since gages on the southeast leg near the target were expected to sense overpressure reinforcement resulting from target reflections, and gages on the north leg were sheltered from the full effect of the blast by the target mass.

Table 4 shows values of TMT equivalent yield in pounds and percentages:

TABLE &. TAT Equivalency Values

Goge Line	Av. yld in 1b THT from peak pressure	Av. , yld from peek pressure	Av. yld in lb T!T From impulse	Av. \$ yld from impulse
Leg 1 (N)	3,300	4.0	3,700	4.5
TUR 2 (N)	4,900	5.9	4,700	5-7
teg 3 (SZ)	8,800	10.8	9,500	11.6
Average*	5,700	6.9	6,000	7-3
Average**	6,440	7.8	5,800	6.3
Average***	6,100	7.4	5,700	7.0

Giving equal weight to each leg.

Yields derived from peak pressure were based on the following formula:

$$W = W_0 \left(\frac{\rho_z}{\rho_0}\right) \left[\frac{Actual distance}{Scaled distance}\right]^3$$

where

W = yield in 1b of TNT

W = 1 1b of TNT

 $\rho_{z} =$ ambient air density

 ρ_{o} = air density at 1,013 mb pressure and 59°P

Actual distance = distance from target impact to gage

Scaled distance = scaled distance corresponding to ratio:

ambient pressure as shown in tabu-

lation in HPN Memo Report \$1518

Giving equal weight to each gage record.

Omitting all records on leg 1, records at 91 and 266 ft on leg 3, and pressure record at 91 ft, leg 2. Equal weight assigned to each of the remaining gage records.

Yields based on impulse data were derived by interpolation between computed TNT weight versus impulse values which, in turn, were derived from the BRL curve used as the source of reference lines on Fig. 22.

In general, the recorded overpressure-time histories were classical in shape; however, a few BRL records exhibited an unusually long rise time to peak pressure. Figure 23 shows typical gage records, four of which are from BRL gages and one is from a Kistler gage. The Kistler gage record at 512 ft on the SE leg was less regular in shape and more difficult to interpret than the record of the Kistler gage at 1,130 ft on the same leg.

Because of inherent limitations, BRL gages at 91 ft on the west and southeast legs had only marginal capability in detecting true peak pressure at this distance from the blast. This may account for the low peak pressure values at 91 ft as contrasted with the trends shown by other gages on the west and southeast legs, and as contrasted with impulse values for the gages at 91 ft.

The relationship between the energy release associated with the propellant reaction at impact and the blast wave is obscured somewhat by other factors, some of which may contribute to the blast wave and some of which detract from it. Two possible contributors are kinetic energy and the rupturing of the motor case as a pressure vessel. The computed kinetic energy contribution combined with the computed rupture action can account for less than 1% of TMT equivalency for the assumed 82,000 lb of propellant at impact. On the other hand, the pro rata division of all available energy into principal effects (i.e., creation of a blast wave, target and motor destruction, and fragment dispersal) is very difficult to determine. It is apparent, however, that energy required for destruction and fragment dispersal is not available for blast wave formations in the atmosphere.

In view of the above, it is considered that the best estimate of TNT equivalency for the test item under the test conditions experienced is 7.5%, plus or minus 2%.




FIG. 1. Target Used in 624A Motor Impact Test.




FIG. 2. Enlarged Film Frame Showing Typical Blast Gage Installation.




FIG. 3. Pressure Gage Location Chart.

TABLE 1. Overpressure Gages

Position (ft)	Leg #1 (North)	Leg go (West)	Leg §! (Southeest)
A 51		Kistier - folk BML - 100 psi	NAL - 50 pel
8 154		Kistler - 601A BPL - 50 pei BPL - 25 psi	982 - 85 p41
560 G		Kistler - GGLA NGL - 15 pai NGL - 5 pai	Mintler - Sold MEL - 15 per MEL - 5 per
275	BL - 5 pel	Kistler - TOLA BML - 5 pai BML - 1 pai	NL -1 pal
1,130	BML - 1 pai	NG 1 psi	Mistler - Mia Mil - C.5 pai
1,900	2012 - 0.5 pml		WL + 015 pax






FIG. 5. Installation of Aft Sled Hing.



FIG. 6. Rotation of Test Motor Before Being Mounted on Track.





FIG. 7. Motor Ready for Firing.






FIG. 8. Enlarged Sequential Film Frames Showing Motor Impact.




FIG. 9. Photographic Sequence After Motor Impact as Viewed From a Distance of 4.1 Miles. Sequence is from top to bottom.




FIG. 10. Typical Pieces of Unburned Propellant.




FIG. 11. Typical Residue From Burned Propellant.



FIG. 12. Forward Closure.



FIG. 13. Debris to East of Target.



FIG. 14. Debris to West of Target.



FIG. 15. Debris to North of Target. Arrow points to position of forward closure shown in closeup view, Fig. 12.




FIG. 16. Debris and Crater at Target Site.






FIG. 17. Target as Viewed From Track Muzzle Before and After Test.




PRACMENT IDENTIFICATION TABLE

Amber .	Description
1	Residue of burned propellant
5	Residue of burned propellant
3	Reaidue of burned propellant
4	Prognent of rear motor closure, approx. 7'x3'
5	Fragment of sled ring, approx. 5.5' long
6	Prognent of notor case, approx. 2.5'x4.5'
7	Pregnent of concrete, approx. 300 1b
8	Fragment of concrete, approx. 12 1b
9	Four marks of burned propellant
10	Two marks of burned propellant
n	Pregnent of motor case, approx. 4'x6'
15	Fragment of motor case, approx. h'xh'
13	Residue of burned propellant
14	Residue of burned propellant
15	Residue of burned propellant
16	Pragment of motor insulation, approx. 18"x15"
17	Pragment of motor insulation, approx. 16"c18"
19	Pragment of motor case, approx. 8'xh'
19	Fragment of motor insulation, approx. 18"x18"
20	Fragment of motor insulation, approx. 24"x18"
21	Prespect of concrete, approx. 50 15 41.
55	Fragment of concrete, approx. 500 16.
23	Fragment of motor, applica. 2'x4'
24	Line of residue from burned propellant
25	Realdor from burned propellant
26	Residue from burned propellant, approx. 5' dism.
27	Pragment of concrete, approx. 150 1b
28	Residue of burned propellant
59	Restine of burned propellant
30	Recidue of burned propellant
31	Fragment of concrete, approx. 200 1b
32	Realthe of burned propellant, approx. 10 ftam.
	·

FIG. 18. Dispersion of Fragments



19.800' N = 1,475'E (2,400' SE of impact point)



22,000' N x 1,200' E (1,240' NE of impact point)



22,100' N x 1,200'E (1,260' NE of impact point)




19,400'N x 500'# (2,800'SW at Impect paint)

FIG. 19. Montage Showing Large Pieces of Debris. (See note on page 4, third paragraph.)

TPR 303 ZEPO TIME SLED FIRST-MOTION MOTOR CHAMBER PRESSURE - 550 psi -TRACK COILS FORWARD RING LATERAL VIBRATIONS AFT RING LATERAL VIBRATION REFERENCE LINE LINEAR ACCELERATION 1.49 FORWARD RING VERTICAL VIBRATIONS AFT RING VERTICAL VIBRATION MOTOR IGNITION IRIG FORMAT B'TIMING NIOO BCT THANG-Flu. d. Sc

TRACK STATION 19,700' N William The Company of the Company o Sections of Telemetry Record Obtained During Test.








FIG. 21. Graph Showing Overpressure Vs. Distance.




FIG. 22. Graph Showing Impulse Vs. Distance.




FIG. 23. Typical Blast Gage Records (Note Scale Variation).

INITIAL DISTRIBUTION

3 Chief, Bureau of Naval Weapons DLI-31 (2)

y-121 (1)

1 Special Projects Office (SP-120, Capt. L. Smith)

2 Chief of Naval Research (Code 104)

1 Naval Missile Center, Point Mugu (Technical Library)

1 Naval Propellant Plant, Indian Head (Dr. C. B. Dale)

20 Space Systems Division, Air Force Systems Command

20 Defense Documentation Center (TISIA-1) 1 Coast and Geodetic Survey (W. V. Mickey)

1 George C. Marshall Space Flight Center, Huntsville (Dr. J. Gayle)

Negative Numbers of Illustrations

Figures:

* ~D~	_ 0.50		
1.	LHL 095525	12.	LHL 095546
2.	LHL 098175	13.	LHL 095536
3.	none	14.	
4.	none	15.	LHL 095538
5.	LHL 095552	16.	LHL 095549
6.	LHL 095554	17.	LHL 096875
7.	LHL 095529	18.	none
8.	LHL 098176	19.	none
9.	LHL 096874	20.	none
10.	LHL 095532	21.	none
11.	LHL 095540	22.	none
		23.	none

624A Solid-Propellant Motor Impact Test, by Robert F. Vorwerk & Frederick H. Weals. China Lake, Calif., U. S. Maval Ordnance Test Station

NOTS, October 1964. 30 pp. (TPR 381, NOTS TP 3674), UNCLASSIFIED.

target at a velocity of 667 figs to determine the haz-ABSTRACT. At the request of the Air Force Systems with a single center segment glus end closures, was impacted into a massive concrete, steel, and earth Command, a preprototype version of the 624A motor,

1 card, 4 copies (Over)

624A Solid-Propellant Motor Impact Test, by Robert F. Vorwerk & Frederick H. Weals. China Lake, Calif., ABSTRACT. At the request of the Air Force Systems NOTS, October 1964. 30 pp. (TPR 381, NOTS IF 3674), Command, a preprototype version of the 624A motor, with a single center segment plus end closures, was impacted into a massive concrete, steel, and earth UNICE ASSIFTED.

U. S. Naval Ordnance Test Station

1 card, 4 copies (over)

target at a velocity of 667 fps to determine the haz-

- はない

624A Solid-Propellant Motor Impact Test, by Robert P. Vorwerk & Frederick H. Weals. China Lake, Calif., MOUS, October 1964. 30 pp. (TPR 381, NOTS TP 3674), U. S. Mayal Ordnence Test Station

UNICLASSIPIED.

ABSTRACT. At the request of the Air Force Systems target at a velocity of 667 fps to determine the hazwith a single center segment plus end closures, was impacted into a massive concrete, steel, and earth Command, a preprototype version of the 624A motor,

U. S. Naval Ordnance Test Station

624A Solid-Propellant Motor Impact Test, by Robert F. Vorwerk & Frederick H. Weals. China Lake, Calif., NOTS, October 1964. 30 pp. (TPR 381, NOTS TP 3674),

UNCLASSIFIED.

target at a velocity of 667 fps to determine the haz-ABSIRACT. At the request of the Air Force Systems with a single center segment plus end closures, was impacted into a massive concrete, steel, and earth Command, a preprototype version of the 624A motor,

1 card, 4 copies (over)

1 card, 4 copies

(over)

gage data indicated a low range of overpressure and impulse forces. Fragments of motor case were thrown to 2,500 ft, and pieces of burning propellant were thrown to 3,000 ft.

This report presents a description of the test setup, procedures, results, and conclusions.

TPR 381

ard potential of the motor. Photographic data showed extensive grain breakup from the impact, and blast-gage data indicated a low range of overpressure and impulse forces. Fragments of motor case were thrown to 2,500 ft, and pieces of burning propellant were thrown to 3,000 ft.

This report presents a description of the test setup, procedures, results, and conclusions.

erd potential of the motor. Photographic data showed

TEN 33

extensive grain breakup from the impact, and blast-

gage data indicated a low range of overpressure and

to 2,500 ft, and pieces of burning propellant were

thron to 3,000 ft.

This report presents a description of the test

setur, procedures, results, and conclusions.

TPR 381

ard potential of the motor. Photographic data shake extensive grain breakup from the impact, and blast-gage data indicated a low range of overpressure and impulse forces. Fragments of motor case were thrown to 2,500 ft, and pleces of burning propellant were thrown to 3,000 ft.

This report presents a description of the test setup, procedures, results, and conclusions.